

1 Q. At page 7 of Hydro's Report in support of its Application, Hydro relates that the
 2 "impedance mismatch" outlined therein results in a "loss" of transformer capacity
 3 in the magnitude of 31.8 MVA.

4
 5 (i) Please explain how such capacity is "lost" and whether there are
 6 alternatives available to recapture such "lost" capacity in the loop short of
 7 installing a new transformer?; and

8
 9 (ii) If there are alternates available to recapture such "lost" capacity, please
 10 provide the manner in which this could be done and a detailed cost estimate
 11 to do so?

12
 13
 14 A. (i) The following table provides the impedance value of each 230/66 kV power
 15 transformer in the Hardwoods – Oxen Pond Loop.

Table 1: Impedance Value
Hardwoods – Oxen Pond Loop
Transformer Impedance Values

Unit	Rating MVA	Impedance %
HWD T1	40/53.3/66.6	8.30
HWD T2	40/53.3/66.6	9.12
HWD T3	40/53.3/66.6	8.45
HWD T4	75/100/125	8.80
OPD T1	40/53.3/66.6	8.85
OPD T2	75/100/125	9.02
OPD T3	75/100/125	8.73

1 Electric current will flow along the path of least impedance. In situations
2 with two or more transformers having the same impedance operate in
3 parallel, the current will be equal in all transformers, and consequently all
4 transformers will reach nameplate rating at the same time as load increases.
5 In situations where there are multiple transformers in parallel with different
6 impedances, such as the transformers in the Hardwoods – Oxen Pond Loop,
7 more current will flow in the transformer with the lowest impedance than in
8 the other units. In essence, the transformer with the lower impedance will
9 carry more than its proportionate share of the total current. As a result, the
10 transformer with the lowest impedance will reach its nameplate rating
11 before the remaining transformers as load increases in the station.

12
13 If one considers the transformers in the Hardwoods Terminal Station and
14 ignores the effects of the connected 66 kV transmission system and the
15 Oxen Pond transformers, Hardwoods T1 is expected to reach 100% of its
16 nameplate rating before T2 through T4. A simple load flow case with the 66
17 kV transmission disconnected and all the load being carried on the
18 Hardwoods 66 kV bus, provides an example of the effects of impedance
19 mismatch on station loading. Figure 1 provides a load flow plot of the
20 Hardwoods Terminal Station with 304 MW of load on the 66 kV bus. One
21 will note that transformer T1 is loaded to 100% of its nameplate rating,
22 while T2, T3 and T4 are loaded to 91%, 98% and 94% of their nameplate
23 ratings respectively. This mismatch in impedances results in approximately
24 16.8 MVA of transformer capacity being unavailable. Increasing the load on
25 the Hardwoods 66 kV bus will result in the loading on T1 exceeding 100% of
26 its nameplate rating before the remaining transformers reach 100% of
27 rating.




Figure 1: Hardwoods Maximum Transformer Loading

1 A similar analysis can be completed for Oxen Pond Terminal Station. Figure 2
 2 provides a simple load flow plot of the Oxen Pond Terminal Station with a 66
 3 kV bus load of 300 MW. One will note that transformer T3 is loaded to
 4 100% of nameplate rating, while T1 and T2 are loaded to 96% and 98% of
 5 their nameplate ratings respectively. This mismatch in impedances results
 6 in approximately 8.2 MVA of transformer capacity being unavailable.
 7 Increasing the load on the Oxen Pond 66 kV bus will result in the loading on
 8 T3 exceeding 100% of its nameplate rating before the remaining
 9 transformers reach 100% of rating.




Figure 2: Oxen Pond Maximum Transformer Loading

1 From these examples it can be seen that variations in impedance of
 2 transformers within the same station result in unequal loading on the units
 3 and consequently transformer capacity that is unavailable to accept load
 4 once the lowest impedance transformer reaches its nameplate rating before
 5 the higher impedance units. These examples show the maximum loading on
 6 the transformers in a station is also dependent upon which, if any, of the
 7 transformers are out of service. Extending this further, if the loads are
 8 moved away from the Hardwoods and Oxen Pond 66 kV buses, and
 9 distributed unevenly around the St. John’s Region by multiple 66 kV
 10 transmission lines with different lengths, paths and impedances, while the
 11 mismatch becomes more complex to calculate, unequal loading of the
 12 Hardwoods and Oxen Pond 230/66 kV transformers remains.

13
 14 From a longer term transmission planning perspective, each of the three 125
 15 MVA transformers in the Hardwoods – Oxen Pond Loop is considered to
 16 have equal opportunity of failure. However, the shift in station loadings and
 17 available transformer capacity to supply the load due to the impedance

1 mismatch is very dependent upon which transformer fails. For the
2 spreadsheet calculations found in the capital budget submission which
3 summarize the Hardwoods – Oxen Pond Loop transformer loading situation
4 and fulfillment of transformer back up criteria, Hydro has calculated a
5 mismatch value of 31.8 MVA to be representative of what can be expected.
6 The 31.8 MVA value is based upon the transformer mismatch with the
7 lowest impedance 125 MVA unit out of service, load redistribution to
8 provide maximum load at each terminal station, and consideration for
9 current rating of the transformers and 230 kV bus voltages at the time of the
10 event.

11
12 Two possible alternatives may be considered to address the loss in available
13 transformer capacity due to impedance mismatch. The first would be to add
14 generation to the 66 kV system to offset the loss. One will note from the
15 capital budget submission that the existing Hardwoods combustion turbine
16 is used to offset a portion of the unavailable/lost transformer capacity
17 associated with the loss of a 125 MVA unit. However, the addition of new
18 combustion turbine and fuel storage facilities may be considered cost
19 prohibitive in comparison to additional transformer capacity if sufficient
20 space is available within existing terminal stations to add such capacity.

21
22 The second alternative considers additional transformer capacity. With
23 respect to adding transformer capacity to offset unavailable capacity due to
24 impedance mismatch, it is worth noting that transformers purchased by
25 Hydro are required to be designed and built according to CAN/CSA-C88-M90
26 “Power Transformers and Reactors”. Section 14 of this standard covers
27 design tolerances. Table 9 of the standard indicates that the tolerance on
28 impedance for a two winding power transformer, like the Hardwoods and

1 Oxen Pond units, is $\pm 7.5\%$ of the guaranteed value. The average value of
2 impedance for transformers in the Hardwoods – Oxen Pond Loop equals
3 8.75%. Specifying a new 230/66 kV transformer with this impedance in
4 attempt to “balance” the transformer impedances to ensure minimum
5 mismatch and maximum transformer capacity availability is not without
6 issue. Despite specifying a new 230/66 kV transformer for the Hardwoods –
7 Oxen Pond Loop with an impedance of 8.75%, the manufacturer can design
8 and build the unit with an impedance ranging between 8.09% and 9.40%
9 and still meet the requirements of the CSA standard with no penalty on the
10 project. If one compares the design tolerance range of 8.09% to 9.40% with
11 the impedances provided in Table 1, one notes the existing transformer
12 impedances more closely match than the tolerance permitted by the
13 standard. While the manufacturer will attempt to design and build a
14 transformer to the exact impedance specified, it is impossible to guarantee
15 that two consecutive transformers of the same design will have the exact
16 same impedance when completed.

17
18 The existence of impedance mismatch on multiple transformer stations is
19 unavoidable, particularly when transformers are purchased at different
20 times and built by different manufacturers. Design and manufacturing
21 techniques today permit the impedances of new units to be within a very
22 tight tolerance.

- 23
24 (ii) Hydro finds no economically viable alternative to eliminate impedance
25 mismatch within the Hardwoods – Oxen Pond Loop short of installation of
26 additional transformer capacity when warranted.