Page 1 of 1

1	Q.	Please detail how the established maintenance test procedures did not adequately
2		validate the system function for the direct current (DC) lubrication oil pump on
3		January 11, 2013.
4		
5		
6	A.	Please refer to the January 11, 2013 root cause analysis report, which is submitted
7		as PLIR-NI H-228 Attachment 1