Q. **Reference: Renew Diesel Units (2027); Response to PUB-NLH-035, Table 1**

Why was warranty coverage not available for units SBN-2075 (100 operating hours at time of failure) and SBN-2055 (251 operating hours at time of failure)?

A. Warranty coverage was not available as the referenced units were not new engines. They were existing engines that were overhauled using new parts completed by internal resources. Warranty eligibility would be considered on a case-by-case basis; however, an Original Equipment Manufacturer ("OEM") will not generally accept warranty work done by non-OEM personnel.