

Undertaking 93

Undertake to provide a list of *(the titles of)* the documentation/information that you received from Hydro on which you carried out your assignment in this proceeding.

The following was provided by Newfoundland and Labrador Hydro to La Capra Associates:

Documents relied upon for writing La Capra Associate's August 7, 2015 Report are footnoted throughout the Report. The documents referenced in the Report and all other documents we were generally aware of are listed below:

- PR-PUB-NLH 001
 - Attachment 1
 - Attachment 2 (CA-NLH-017)
- PR-PUB-NLH 002
 - Attachment 1 (NP-NLH-022-Rev-1) – AMEC Report Conclusions
 - Attachment 2 (PUB-NLH-022) – Holyrood Blackstart Diesel Units Application
 - Attachment 3 (PUB-NLH-012) – Holyrood Blackstart Diesel Units Application
- PR-PUB-NLH 003
 - Attachment 1 (IC-NLH-010) – Holyrood Blackstart Diesel Units Application
 - IC-NLH-010 – Attachment 1 (Holyrood Blackstart) – HTGS Procedures
 - IC-NLH-010 – Attachment 2 (Holyrood Blackstart) – HTGS Procedures
 - IC-NLH-010 – Attachment 3 (Holyrood Blackstart) – Power System Outage Report – Dec.8 to Dec. 11 1994
 - IC-NLH-010 – Attachment 4 (Holyrood Blackstart) – Update to Board on Status of Remedial Actions Arising Out of December 1994 Outage
 - IC-NLH-010 – Attachment 5 (Holyrood Blackstart) – Hydro Response to Board from October 17, 2013 letter addressing black start at HTGS
 - Analysis of Options to Provide Black Start Capability to Holyrood Thermal Generating Station
- PR-PUB-NLH 004
- PR-PUB-NLH 009
- PR-PUB-NLH 010
- PR-PUB-NLH 103
- PR-PUB-NLH 104-Rev-1
- PR-PUB-NLH 105
- PR-PUB-NLH 106
- PR-PUB-NLH 107
- PR-PUB-NLH 108
- PR-PUB-NLH 109
- PR-PUB-NLH 110
- PR-PUB-NLH 111
- PR-PUB-NLH 112
- PR-PUB-NLH 113

- PR-PUB-NLH 114
- PR-PUB-NLH 115
- PR-PUB-NLH 116
- PR-PUB-NLH 123
- PR-PUB-NLH 124
- PR-PUB-NLH 125
- PR-PUB-NLH 126
- PR-PUB-NLH 127
- PR-PUB-NLH 128
- PR-PUB-NLH 129-Rev-2
- PR-PUB-NLH 130
- PR-PUB-NLH 131
- PR-PUB-NLH 172
 - Attachment 1 (Holyrood Back Start – Motor Start Simulation) Conclusion
- PR-PUB-NLH 173
 - Attachment 1 (PUB-NLH-023) - Holyrood Blackstart Diesel Units Application
 - Attachment 1 – Events of January 2013 Power System Outage Report
 - Attachment 1 – January 11, 2013 – Winter Storm Events - Power System Sequence of Events
 - Attachment 1 (PUB-NLH-003) - Island Interconnected System Supply Issues and Power Outages
 - Unit 1 Failure – Holyrood (Line Safety Review)
 - January 11, 2013 Winter Storm Events (Power System Performance Review Report)
 - January 11, 2013 Winter Storm Events (Power System Performance Review Recommendations Resulting from the Analysis Indicated by Area)
 - Remedial Actions From the January 1, 2013 System Events
 - Attachment 1 (PUB-NLH-081) - Island Interconnected System Supply Issues and Power Outages
 - Attachment 2 (CA-NLH-025) - Holyrood Blackstart Diesel Units Application
 - Attachment 2 (PUB-NLH-160) - Island Interconnected System Supply Issues and Power Outages
 - Attachment 3 (Hydro Response to Board letter from July 23, 2013 about Board’s questions)
 - Attachment 4 (Formal Request to use Newfoundland Power Mobile Units)
 - Attachment 5 (Holyrood Black Start Capability)
 - Attachment 6 (Holyrood Black Start Capability) – Response to October 17, 2013 letter from Board
 - Analysis of Options to Provide Black Start Capability to Holyrood Thermal Generating Station
- PR-PUB-NLH 174
- PR-PUB-NLH 175
- PR-PUB-NLH 176
- PR-PUB-NLH 177

- PR-PUB-NLH 178
- PR-PUB-NLH 179
- PR-PUB-NLH 180
- PR-PUB-NLH 181-Rev-1
- PR-PUB-NLH 182-Rev-1-Redacted
- PR-PUB-NLH 183-Rev-1
- PR-PUB-NLH 184
- PR-PUB-NLH 196
- PR-PUB-NLH 199
- PR-NLH-PUB-013
- PR-NLH-PUB-014
- PR-NLH-PUB-015
- PR-NLH-PUB-016
- PR-NLH-PUB-017
- PR-NLH-PUB-018
- PR-NLH-PUB-019
- EASA Standard AR100-2010
- Liberty Consulting - Prudence Review of Newfoundland and Labrador Hydro Decisions and Actions Final Report (July 6, 2015)
- NLH2009Application-Volumell-Report21 (Hardwoods Gas Turbine Plant Life Extension Upgrades Report)
- Operating Instructions T007 and T022
- 2012 Capital Budget Application, Volume I
- NP-NLH-022-Rev 1, Attachment 1
- 2013 08 05 Black Start Capability Responses to PUB Questions 1-5
- Guidelines for Maintaining Steam Turbine Lubrication Systems - EPRI – 1986
- <http://www.pub.nf.ca/applications/nlhcbst2013/HolyroodDieselPU33/index.htm>
- <http://www.pub.nf.ca/applications/nlhcbst2013/unit1refurb/index.htm>

In addition to the above, La Capra Associates had various clarification discussions with Hydro from the information provided.