Page 1 of 1

O:	Reference: Review of Newfoundland and Labrador Hydro Power Supply
· ·	Adequacy and Reliability Prior to and Post Muskrat Falls Final Report, Page 2.
	"As directed by the Board for the scope of the phase two investigation, we did not
	address detailed technical information or project engineering and construction
	issues, except as necessary to understand the reliability risks associated with the
	interconnection to the IIS."
	Please confirm whether or not Liberty obtained data from Hydro relative to the
	structural/mechanical reliability of the Labrador Island Link. If so, please provide the data obtained from Hydro.
A.	Liberty did not seek to obtain, nor did we receive, data related to the struc
i	mechanical reliability of the Labrador Island Link.
	Q: