1	L	Q.	Reference: Volume II, 2023 Capital Budget Application, Program 14, Upgrade of Worst-
2	2		Performing Distribution Feeders (2023–2024), page 6, lines 7 to 10.
3	3		Has Hydro considered installing remotely monitored and controlled down line reclosers instead
2	1		of gang operated switches to reduce outage time? If not, why not?
5	5		
6	õ		
7	7	A.	Three remote controlled protective devices are already installed at Farewell Head (FH1-CB1) and
8	3		Change Islands (FH1-R1/R2). The replacement of the two gang operated switches proposed
g	9		within this program with remotely controlled reclosers was not required as there were no
10)		customers between the switch locations and the existing devices that could benefit from
11	l		additional automatic sectionalizing; thus, the extra cost could not be justified.