Page 1 of 1

- 1 Q. Have substation inspection, repair (CM), and preventive maintenance (PM)
  2 practices changed since 2009? Are there any changes beginning in 2014? Please
  3 describe in detail any changes in terminal station/substation inspection and
  4 maintenance practices including changes beginning in 2014.
- A. Substation inspection and maintenance (CM and PM) practices have not materially changed since 2009. As was indicated in the response to Request for Information PUB-NP-066, Tap 4 Vibration Analysis was included as part of the inspection process beginning in 2012.
- There are no changes planned to the substation inspection and maintenance practices for 2014.