Filed: 2025-September-26

Service Failures, Miscellaneous Upgrades and Street Lights (2026)

Page 6, Table 1 shows that the post implementation impact is reduced to 1. Explain the factors that have led to this estimated reduction.

The post-implementation impact value of 1 provided in the Distribution System In-Service Failures, Miscellaneous Upgrades and Street Lights (2026) Program is a typographical error—the value should read as 3. The revised Table 1 is as follows:

Reference: Schedule 7: Capital Programs and Projects, Program 2: Distribution System In-

Q.

1

Table 1: Risk Scoring Pre- and Post-Implementation

	Impact	Likelihood	Score
Pre-Implementation	3	5	15
Post-Implementation	3	1	3
	Risk Mitigated		12
Risk Mitigated per \$1 Million		2.0	